

# ***HELLPER***

Value in Every Solution.



# **MITSUBISH CATALOG**

[www.hellperglobal.com](http://www.hellperglobal.com)

| OEM                                                                              | TYPE        | PICTURE                                                                             | CAR MODEL                                      | YEAR  | Remark                                 |
|----------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|------------------------------------------------|-------|----------------------------------------|
| MB241171<br>MB315775<br>MR241032<br>HB568120<br>SB000037<br>MB166765<br>S2370706 | Tie Rod End |    | PAJERO L300<br>4WD L200<br>STRADA K64T         | 1982- | SE-7771<br>SE-7251<br>CEM-9<br>ES2246L |
| MB831043<br>MR296275                                                             | Tie Rod End |    | PAJERO                                         | 1990- | SE-7721<br>ES3386RL<br>CEM-27          |
| MB347599                                                                         | Tie Rod End |    | DELICA                                         | 1992- | SE-7331                                |
| MB347600                                                                         |             |                                                                                     |                                                |       | SE-7332                                |
| MR508136<br>4422A010T<br>4422A010<br>MR961981<br>4422A096                        | Tie Rod End |  | TRITON 4x4 PAJERO<br>V88 V65 PAJERO<br>L200T   | 1999- | SE-7841R<br>CEM-51R                    |
| MR508135<br>4422A009T<br>4422A009<br>MR961980                                    |             |  |                                                |       | SE-7841L                               |
| MR162710<br>MB347599<br>56872-43010<br>MB864164<br>56872-43000<br>MB527650       | Tie Rod End |  | DELICA SPACE<br>GEAR                           | 1992- | SE-7331<br>SE-7761<br>CEM-38           |
| MA169613<br>MA159982<br>56810-11020<br>56820-11000                               | Tie Rod End |  | GLANT LANCER                                   | 1973- | SE-7072<br>ES2195R                     |
| MW033300<br>MC891647                                                             | Tie Rod End |  | MITSUBISHI CANTER T210<br>MITSUBISHI CANTER FC | 1973- | CEM-7L                                 |
| MW033301<br>MC891648                                                             |             |                                                                                     |                                                |       | CEM-7R                                 |
| MB633226<br>MB633225                                                             | Tie Rod End |                                                                                     |                                                |       |                                        |
| MR267445<br>MR319875                                                             | Tie Rod End |  | ADVENTURE FREECA 富利卡                           | 1998- | SE-7781L                               |
| MR319876<br>MR319390                                                             |             |                                                                                     |                                                | 开发    | SE-7781R                               |

|                                                                                                                   |              |                                                                                     |                                                                                           |                            |       |                              |
|-------------------------------------------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|----------------------------|-------|------------------------------|
| 4422A008T<br>4422A016<br>4422A008                                                                                 | Tie Rod End  |    | TRITON 4x2<br>TRITON KA4T                                                                 | ZINGER                     | 2005- | SE-7941                      |
| MB166982<br>MA159984<br>MA169614<br>MB378704<br>MB122782<br>MB122781<br>56810-11060<br>56810-11000<br>56810-11020 | Tie Rod End  |    | GLANT LANCER<br>DODGE CHALLENGER<br>CHRYSLER CONQUEST<br>PLYMOUTH TRUCK ARROW<br>蓝瑟 小马 戈蓝 |                            | 1973- | SE-7071<br>ES2194R<br>CEKH-2 |
| MB241206<br>MB315776<br>MR296274<br>SB000036<br>MB166766<br>HB568110<br>S2370704<br>SB000036<br>HB568110          | Tie Rod End  |    | GALLOPER<br>L300                                                                          | PAJERO<br>4WD L200         | 1980- | SE-7252<br>CEM-10            |
| MB243426A<br>HB568200<br>HB568100<br>MB243425A                                                                    | Rod Assembly |    | HYUNDAI GALLOPER                                                                          |                            |       |                              |
| MB162810                                                                                                          | Tie Rod End  |  | MITSUBISHI L300<br>Platform/Chassis P1_T<br>MITSUBISHI SPACE GEAR<br>PA/B/D_V/W           |                            |       | CEM-18R<br>SE-7361R          |
| MB162811                                                                                                          |              |                                                                                     |                                                                                           |                            |       | CEM-18L<br>SE-7361L          |
| MB564855                                                                                                          | Tie Rod End  |  | DELICA<br>Ram50<br>Max                                                                    | Dodge<br>Mitsubishi Mighty | 1992- | SE-7731<br>ES3156RL          |
| MB831044<br>MB831274                                                                                              | Tie Rod End  |  | PAJERO                                                                                    |                            | 1990- | SE-7722<br>ES3387RL          |
| MC805517<br>MC810258<br>13501-13500<br>13501-13000<br>MC832322<br>MK428157                                        | Tie Rod End  |  | MITSUBISHI FUSO TRUCK<br>FK315 FK316 FK415 FK416<br>FK425<br>FK515 FK516                  |                            | 1984- | SE-7341L                     |
| MC805518<br>MC810259<br>13501-13600<br>13501-13100<br>MC832323<br>MK428158                                        |              |                                                                                     |                                                                                           |                            |       | SE-7341R                     |

|                                                                                            |             |                                                                                     |                                                                                           |       |                               |
|--------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-------|-------------------------------|
| MK309712<br>MK309192<br>MC891913<br>MC891398<br>MK384673<br>MK997629                       | Tie Rod End |    | MITSUBISHI CANTER                                                                         | 1973- | SE-7831R<br>CEM-54            |
| MK997628<br>MK384672<br>MC891397<br>MC891912<br>MK309191<br>MK309711                       |             |                                                                                     |                                                                                           |       | SE-7831L<br>CEM-53            |
| MK996332<br>MK997508<br>ML106234<br>MK309709<br>MK384667<br>MK309189                       | Tie Rod End |    | CANTER FE5                                                                                | 1993- | SE-7891L                      |
| MK996333<br>MK997509<br>ML106235<br>MK309710<br>MK38466                                    |             |                                                                                     | CANTER FE5                                                                                |       | SE-7891R                      |
| 4422A037                                                                                   | Tie Rod End |   | PAJERO V83W                                                                               | 2005- | SE-B041L                      |
| 4422A038                                                                                   |             |                                                                                     |                                                                                           |       | SE-B041R                      |
| 4422A018<br>MR491380<br>4422A002<br>MR548285<br>MR508650<br>MH161007<br>MN161077<br>381774 | Tie Rod End |  | OUTLANDER CW5W<br>GALANT FORTIS CY4A<br>OUTLANDER<br>CITROËN C-CROSSER EP<br>PEUGEOT 4007 | 2002- | SE-B011<br>ES800471<br>CEM-49 |
| ES3704<br>MR476457                                                                         | Tie Rod End |  | Mitsubishi Lancer                                                                         | 2004- |                               |
| MR241031<br>MB564853                                                                       | Tie Rod End |  | STRADA K64T<br>DELICA<br>50 Dodge Ram<br>Mitsubishi Mighty Max                            | 1992- | SE-7732<br>ES3157<br>CEM-26   |

|                                                                                                                                                                                                                                                                                                     |             |                                                                                     |                                                                                                                                 |       |                                         |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------|-------|-----------------------------------------|
| MB166427<br>MB076532<br>MB006359<br>MB006315<br>MT142182<br>MB241207                                                                                                                                                                                                                                | Tie Rod End |    |                                                                                                                                 | 1968- | SE-7162<br>CEM-3L                       |
| MB166426<br>MB315629<br>MB185441<br>MB006358<br>MB006314<br>MT142181<br>MB241172<br>6127716<br>1476246<br>MB315629<br>56820-21110<br>56820-21100<br>56820-31000<br>56820-21120<br>56820-21000<br>MB076531<br>MB912887<br>48520-6A0A0<br>MR476457<br>MR535996<br>56820-28000<br>MB597605<br>MB598023 | Tie Rod End |    | L300<br>FIORE<br>LANCER<br>CLIPPER MA0<br>COLT<br>EXCEL<br>CHAMP<br>LANCER-<br>MIRAGE<br>LANCER<br>DODGE<br>HYUNDAI<br>PLYMOUTH | 1984- | SE-7301<br>SE-7161<br>ES2171R<br>CEM-3R |
| MB527169<br>MB241982<br>MB597605<br>MB598023<br>MB912076<br>MR476457<br>MR485672<br>MB489407<br>510185<br>30870695<br>PW510185                                                                                                                                                                      | Tie Rod End |  | LANCER MIRAGE                                                                                                                   | 1983- | SE-7241                                 |
| MB288119                                                                                                                                                                                                                                                                                            | Tie Rod End |  | MITSUBISHI DELICA Box P0_W<br>P1_W<br>L300 Platform Chassis L03_P<br>MITSUBISHI                                                 | 1982- | SE-7262                                 |

|                                                                                                                                                                                                                                                                        |             |                                                                                     |                                                                                                                           |                                                                                     |                                                                        |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| MB564991<br>MB192430<br>MB489434<br>MB192499<br>MB616286<br>MB573885<br>MB912519<br>2692791<br>MB912520<br>56820-36000<br>56882-44000<br>56882-44002<br>56820-M2000<br>56820-3B000<br>30875012<br>4422A028<br>MR476457<br>MR535996<br>MB535996<br>MR485672<br>MR598023 | Tie Rod End |    | L300 GALANT<br>CHRYSLER SEBRING<br>DODGE 2000 GTX<br>HYUNDAI ELANTRA 飞腾                                                   | 1996-                                                                               | SE-7261<br>SE-7231<br>ES2347RL<br>ES3389<br>CEKH-6<br>ES2906<br>ES3616 |
| MB122011<br>MB122012                                                                                                                                                                                                                                                   | Tie Rod End |   | FORTE L200                                                                                                                | 1978-                                                                               | SE-7152R<br>ES2199R                                                    |
| MB076663<br>MB076003<br>MB122779<br>MB166980<br>MB378701                                                                                                                                                                                                               |             |  | Mitsubishi Mighty Max<br>Chrysler Conquest Dodge<br>Ram 50 MITSUBISHI L200<br>MITSUBISHI GALANT A12<br>MITSUBISHI SAPPORO | 1976-                                                                               | ES2197R<br>SE-7112L                                                    |
| MB378702<br>MB076664<br>MB076004                                                                                                                                                                                                                                       |             |  |                                                                                                                           |                                                                                     | ES2428R<br>SE-7112R<br>ES2198L                                         |
| MB076001<br>MB076002                                                                                                                                                                                                                                                   |             |                                                                                     |                                                                                                                           |                                                                                     | SS-7110L<br>SS-7110R                                                   |
| MB527650<br>MB864164<br>SE000327<br>56872-43000<br>MB910859<br>MR376500<br>MB347599                                                                                                                                                                                    | Tie Rod End |  | Mitsubishi 3000 GT<br>Hyundai H-1 Hyundai<br>Porter                                                                       | 1986-                                                                               | SE-7311                                                                |
| MC320345                                                                                                                                                                                                                                                               | Tie Rod End |  | MITSUBISHI 4D35                                                                                                           |                                                                                     | CEM-141                                                                |
| MK363168<br>MK363170<br>MC063775                                                                                                                                                                                                                                       |             |                                                                                     | MITSUBISHI CANTER FD5<br>FG50E                                                                                            |                                                                                     | CEM-141<br>SE-7921L                                                    |
| MK363169<br>MC063776<br>MK363171                                                                                                                                                                                                                                       |             |                                                                                     |                                                                                                                           |                                                                                     | SE-7921R                                                               |
| MK428082<br>MC891387                                                                                                                                                                                                                                                   |             |                                                                                     | Tie Rod End                                                                                                               |  |                                                                        |
| MK428083<br>MC891388                                                                                                                                                                                                                                                   |             |                                                                                     |                                                                                                                           |                                                                                     |                                                                        |

|                                                                                                                                                                                               |            |                                                                                     |                                                                   |                        |       |                              |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------|------------------------|-------|------------------------------|
| MR178817<br>MB527349<br>MB527350<br>MB598547-01<br>MR241632<br>MB598548-01<br>MR273689-01<br>MR376528-1<br>MR273690-1<br>MR376527-1<br>54417-4B000<br>MR2416321<br>54417-4A000<br>54417-43A00 | Ball Joint |    | L300 4WD<br>P25W<br>得利卡上                                          | P23W<br>SPACE GEAR     | 1986- | SB-7761                      |
| MB241885                                                                                                                                                                                      | Ball Joint |                                                                                     |                                                                   |                        |       | 有样品                          |
| MB527383-01<br>MB527384-01<br>SB430000-3                                                                                                                                                      | Ball Joint |    | L300 P01V<br>球头                                                   | 得利卡下                   | 1986- | SB-7312                      |
| MB831037<br>MR296269<br>MR208663                                                                                                                                                              | Ball Joint |   | PAJERO                                                            |                        | 1990- | SB-7722L                     |
| MB831038<br>MR296270<br>MR208664                                                                                                                                                              | Ball Joint |  |                                                                   |                        |       | SB-7722R<br>CBM-23R          |
| MR496799<br>4013A090<br>4013A087T-1<br>4013A088T-1<br>4013A211<br>MR992299                                                                                                                    | Ball Joint |  | PAJERO<br>4WD<br>ZINGER                                           | TRITON<br>PAJERO L200T | 1999- | SB-7842<br>K90673<br>CBM-33  |
| AW330961<br>AW345993<br>54503-34A00<br>54530-37000<br>54503-34A01<br>54530-37010                                                                                                              | Ball Joint |  | MITSUBISHI Diamante<br>HYUNDAI NATA III Y-3                       |                        | 1993- | K500086<br>CBKH-14<br>CBM-19 |
| MR508130<br>4110A072<br>4110A073                                                                                                                                                              | Ball Joint |  | MITSUBISHI PAJERO CLASSIC<br>V2W MITSUBISHI PAJERO III<br>V60 V70 |                        | 2001- | K500096<br>SB-7845<br>CBM-34 |
| MB527511-01<br>MB860408-01<br>MB527512-01<br>MB527157-01<br>MB527161-01<br>MB518283                                                                                                           | Ball Joint |  | FORTE L200 2WD 4WD<br>Mitsubishi Mighty Max<br>Ram 50             | Dodge                  | 1986- | SB-7155<br>K9470<br>CBM-20   |
| MB527511                                                                                                                                                                                      | Ball Joint |                                                                                     |                                                                   |                        |       |                              |
| 54524-43001                                                                                                                                                                                   | Ball Joint |  | HYUNDAI H100 Bus P<br>HYUNDAI H100 Box                            |                        |       |                              |

|                                                                      |            |                                                                                     |                                                                                                                                 |       |                                                                       |
|----------------------------------------------------------------------|------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------|-------|-----------------------------------------------------------------------|
| MB633226                                                             | Ball Joint |    |                                                                                                                                 |       |                                                                       |
| MB633225                                                             |            |                                                                                     |                                                                                                                                 |       |                                                                       |
| MN125871<br>4013A282<br>3520X9<br>05105040AA                         | Ball Joint |    | MITSUBISHI OUTLANDER CW<br>W MITSUBISHI ANT FORTIS<br>Saloon CY/Z_A<br>PEUGEOT 4007 GP<br>JEEP COMPASS/PATRIOT<br>DODGE CALIBER | 2006- | K500063<br>5105040A<br>B                                              |
| MR210438                                                             | Ball Joint |    | MITSUBISHI KUDA<br>ADVENTURE VA1W 富利卡<br>DONGNAN (SOUEAST)<br>FREECA                                                            | 2000- | SB-7782<br>CBM-26                                                     |
| MR1628041<br>MB912505-1<br>MR162803-1<br>MB912505-01                 | Ball Joint |    | MITSUBISHI GALANT V E5_A,<br>E7_A E8_A<br>MITSUBISHI GALANT V Saloon<br>E5_A E7_A E8_A                                          | 1992- | SB-7751                                                               |
| MR162699                                                             | Ball Joint |   | SPACE GEAR L300 L400<br>MITSUBISHI SPACE GEAR<br>PA/B/D_V/W                                                                     | 1994- | SB-7762                                                               |
| MB349907                                                             | Ball Joint |  | MITSUBISHI MINICAB<br>U11#for/Disk                                                                                              | 1984- |                                                                       |
| MB349908                                                             | Ball Joint |  |                                                                                                                                 |       |                                                                       |
| MB109169<br>54540-21A00<br>54540-21000<br>54503-21000<br>54540-21100 | Ball Joint |  | MITSUBISHI COLT I A15A<br>HYUNDAI PONY Saloon<br>DODGE COLT<br>PLYMOUTH CHAMP                                                   | 1976- | SB-7142R<br>K9089<br>CBM-6R                                           |
| MB109168<br>54530-21A00<br>54530-21000<br>54502-21000<br>54530-21100 | Ball Joint |  |                                                                                                                                 |       | SB-7142L<br>K9091                                                     |
| MB185329                                                             | Ball Joint |  | MITSUBISHI GALANT II A16<br>MITSUBISHI SAPPORO II A16A<br>MITSUBISHI STARION A18_A                                              | 1980- | K9143<br>SB-7172<br>10387<br>CBM-10                                   |
| MB175544<br>MB109588<br>MB109587                                     | Ball Joint |  |                                                                                                                                 |       | K9296<br>CBM-4                                                        |
| MB176308<br>MB527352<br>MB527351<br>ZB212100<br>HB212200<br>HB212100 | Ball Joint |  | PAJERO L300<br>4WD P23V L200                                                                                                    | 1986- | SB-7322R<br>SB-7322L<br>SB-7252<br>K9009<br>10384<br>CBM-7<br>CBM-15R |



|                                                                                                                                           |            |                                                                                     |                                                                                                                 |       |                                               |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|-------|-----------------------------------------------|
| MB860829<br>MB860830                                                                                                                      | Ball Joint |    | PAJER                                                                                                           | 1990- | SB-7721<br>K9753<br>CBM-22                    |
| MR403420-1<br>MR403419-1<br>4013A009-1<br>4013A010-1<br>MR961392-1<br>MN101742-1<br>MR961391-1<br>MN101741-1<br>4013A282-1<br>4013A281-1  | Ball Joint |    | LANCER<br>OUTLANDER CW5W                                                                                        | 2000- | SB-7872<br>CBM-36                             |
| MB109587<br>MB175544<br>MB109588                                                                                                          | Ball Joint |    | MITSUBISHI L300<br>Platform/Chassis L03_P<br>MITSUBISHI L300 Bus<br>LO3_P/G, L0_2P<br>MITSUBISHI L300 Box L03_P |       | SB-7152<br>CBM-4<br>K9296                     |
| MK332301<br>MC120301<br>MK331600<br>MK471886                                                                                              | Ball Joint |    | MITSUBISHI CANTER<br>FA/FB/FE MITSUBISHI<br>CANTER FD5                                                          |       | SB-7921<br>SB-7911                            |
| MK332302<br>MC120018<br>MK471893<br>MK471892                                                                                              | Ball Joint |   | MITSUBISHI CANTER FD5/FG                                                                                        | 1999- | SB-7922                                       |
| MK469290                                                                                                                                  | Ball Joint |  | MITSUBISHI CANTER<br>FA/FB/FE                                                                                   |       |                                               |
| MK332303<br>MC120887<br>MK469291<br>MK333373                                                                                              | Ball Joint |  | MITSUBISHI CANTER<br>FA/FB/FE                                                                                   |       |                                               |
| MR496792<br>4010A013T<br>4010A014T<br>4010A015T<br>4010A099<br>4010A015                                                                   | Ball Joint |  | PAJERO TRITON<br>4WD FRONT PAJERO<br>L200T V83W                                                                 |       | SB-7841<br>K500092<br>CBM-32                  |
| MB176309<br>MB349475-01<br>MB241155-01<br>MB241156-01<br>MB349575-01<br>54431-44000<br>54417-44000<br>54431-44000<br>MB176379<br>MB109640 | Ball Joint |  | PAJERO L200<br>L300 MINICAB<br>L013P 富利卡                                                                        | 1980- | SB-7153<br>SB-7282<br>K9372<br>10377<br>CBM-8 |

|                                                                                                                                                                                                                                                                                                                                                               |            |                                                                                     |                                                                                                                                      |       |                                       |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|-------|---------------------------------------|
| MB001699<br>MB001715<br>MB001696<br>MB002588<br>MB430350<br>MB002310<br>54520-14200<br>54530-11000<br>54520-11011<br>54530-14200                                                                                                                                                                                                                              | Ball Joint |    | HYUNDAI PONY<br>HYUNDAI PONY X-2<br>HYUNDAI PONY Wagon<br>HYUNDAI PONY Saloon<br>MITSUBISHI GALANT I A12<br>MITSUBISHI GALANT II A16 | 1973- | SB-7102<br>10348<br>K9077<br>CBKH-1   |
| MT141195<br>MT141196<br>MB109993                                                                                                                                                                                                                                                                                                                              | Ball Joint |    | MITSUBISHI DELICA L300                                                                                                               | 1968- | SB-7082                               |
| MR508130<br>4110A072<br>4110A073                                                                                                                                                                                                                                                                                                                              | Ball Joint |    | MITSUBISHI PAJERO CLASSIC<br>V2_W<br>MITSUBISHI PAJERO III V60<br>V70                                                                | 1999- | SB-7845<br>CBM-34<br>K500096          |
| MB002303<br>MB002583-01<br>MB002584-01                                                                                                                                                                                                                                                                                                                        | Ball Joint |    | MINICAB L013P                                                                                                                        | 1980- | SB-7281                               |
| AW311699<br>MB303374<br>MB303375<br>MB430350/1<br>MB241883<br>MB349963-01<br>MB349964-01<br>MB518205-01<br>MB518206-01<br>MB573093-01<br>MB573094-01<br>MB573098-01<br>MB518041-01<br>MB518042-01<br>MR179479-01<br>MR179480-01<br>MN133617-01<br>MN133618-01<br>MB891788-01<br>MB891787-01<br>MB860817-01<br>MB518960-01<br>MB891788<br>MB912078<br>MB891787 | Ball Joint |  | GALANT<br>MIRAGE<br><br>LANCER<br>STARION                                                                                            | 1982- | SB-7232<br>CBM-11<br>CBM-12<br>CBM-18 |
| MB109585<br>MB002476<br>MB002475<br>MB112476<br>MB112477<br>MR319669<br>MR210442                                                                                                                                                                                                                                                                              | Ball Joint |  | MITSUBISHI L300 Bus LO3_P/G<br>LO_2P<br>MITSUBISHI L300 Box LO3_P                                                                    | 1976- | SB-7151<br>10372<br>K9044<br>CBM-3    |
| MB942086<br>MB912505-1<br>MR162803-1<br>MR162804-1<br>MB912506-1<br>J25004YMT                                                                                                                                                                                                                                                                                 | Ball Joint |  | CHRYSLER SEBRING JX<br>DODGE AVENGER BASE<br>MODEL EAGLE TALON BASE<br>MODEL MITSUBISHI ECLIPSE<br>BASE MODEL                        | 1992- | SB-7751<br>K90264<br>CBM-27           |


|                                                                                                                                           |                  |                                                                                     |                                                                                                                                                                                                                                             |       |                                                |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------------------------------------------------|
| 4010A017T<br>4010A017T-1<br>4010A018T-1<br>4010A019-01<br>4010A020-01<br>4010A014T-1                                                      | Ball Joint       |                                                                                     | TRITON KA4T<br>ZINGER L200<br>KB_T KA_T)                                                                                                                                                                                                    | 2005- | SB-7941                                        |
| MB241974<br>MR392730<br>MR954888<br>54825-24010<br>MB001626<br>MB001925<br>MB109584<br>MB241429<br>3879218<br>1CZ5Z486A                   | Stabilizers Link |    | MITSUBISHI COLT II C1A<br>Chrysler Sebring MITSUBISHI<br>LANCER III C1A C6A<br>Dodge Stratus<br>MITSUBISHI LANCER V CB DA<br>MITSUBISHI LANCER V Station<br>Wagon CBW CDW                                                                   | 1982- | K90308<br>K700528<br>K700530<br>K3105<br>K9231 |
| MB527385                                                                                                                                  | Stabilizers Link |    | DELICA DE2.0 2.5<br>MITSUBISHI L300 Platform<br>Chassis P1_T MITSUBISHI<br>L300 Bus P0_W P1_W P2_W<br>MITSUBISHI DELICA Box P0_W<br>P1_W 得利卡                                                                                                | 1994- |                                                |
| MB809355<br>PW521020                                                                                                                      | Stabilizers Link |   | LANCER VIRAGE<br>F                                                                                                                                                                                                                          | 1993- | SL-7355                                        |
| MB808076<br>4056A013<br>MB573540                                                                                                          |                  |  | MITSUBISHI CHARIOT SPACE<br>WAGON GRANDIS N33W<br>N43W 1                                                                                                                                                                                    | 1991- | K750067                                        |
| MB672370<br>4056A012                                                                                                                      | Stabilizers Link |  |                                                                                                                                                                                                                                             |       | K750068                                        |
| MB584467<br>MB573210<br>4056A039<br>MB864317<br>MB185476<br>MB241881<br>MR131733<br>0916510002<br>0916914008<br>0932010024<br>46630-60B00 | Stabilizers Link |  | MITSUBISHI DELICA PD4W<br>PD6W PD8W<br>MITSUBISHI L400 SPACE<br>GEAR PD4 PD5W<br>MITSUBISHI PAJERO I<br>L041GL149G<br>MITSUBISHI L400 PA3W/PA4W<br>MITSUBISHI DELICA SPACE<br>GEAR/CARGO PA/PB/PC ,<br>MITSUBISHI L300 P0 P1 P2<br>P45V L03 | 1994- | K80877<br>K7402                                |
| MB518780<br>MB518781<br>MB573540<br>4056A040<br>4056A038<br>MR319147                                                                      | Stabilizers Link |  | LANCER<br>MIRAGE<br>OUTLANDER 4WD 2.4L<br>MIRAGE C15A 欧蓝德                                                                                                                                                                                   | 1987- | SL-7390                                        |
| 4056A052<br>2M515E494A<br>B<br>98AG5495AB<br>2M515E494A<br>A 1136725                                                                      | Stabilizers Link |  | MITSUBISH COLT<br>FORD FOCUS C-MAX 福克斯                                                                                                                                                                                                      | 2004- |                                                |
| MB912655<br>MF140269<br>MF100055<br>MB175548<br>MB598097                                                                                  | Stabilizers Link |  | STRADA K64 FRONT<br>L200 PAJERO 帕杰罗                                                                                                                                                                                                         | 1982- | 101-6699                                       |

|                                                                                        |                  |                                                                                     |                                                                                         |       |                            |
|----------------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-------|----------------------------|
| MB892982<br>MB573043<br>MB518892<br>4056A014<br>MB154199<br>54830-28000<br>54830-37010 | Stabilizers Link |    | GALANT E52A E55A F34A<br>GALANT DIAMANTE                                                | 1992- | SL-7755<br>K9475<br>K90186 |
| MR992191<br>4056A133                                                                   | Stabilizers Link |    | PAJERO V93W                                                                             | 2007- | SL-B040L                   |
| MR992192<br>4056A134                                                                   |                  |                                                                                     |                                                                                         | V73   | SL-B040R                   |
| 54618-EN000<br>54618-ET00A<br>54618-CY00A                                              | Stabilizers Link |    | SERENA C25 B16X<br>SERENA JUKE F15                                                      | 2006- | SL-N220                    |
| MB672370                                                                               | Stabilizers Link |    | CHARIOT                                                                                 |       |                            |
| MB633926<br>30873100                                                                   | Stabilizers Link |    | MONTERO V31 V32 V33<br>PAJERO                                                           | 1992- | K750134                    |
| MR267874<br>MR150705                                                                   | Stabilizers Link |   | MITSUBISHI SPACE GEAR PA/B/D V/W<br>MITSUBISHI L400 SPACE GEAR PD4W/PD5W                | 1995- |                            |
| MR132707<br>MR267873                                                                   |                  |  | MITSUBISHI L300-TRUCK P13T/P15T<br>MITSUBISHI L400 PA3W/PA4W<br>MITSUBISHI DELICA SPACE |       | SL-7760<br>CLM-17          |
| MK382984                                                                               | Stabilizers Link |  | CANTER FE83                                                                             | 2002- | SL-7970L<br>CLM-27         |
| MK382985                                                                               |                  |                                                                                     |                                                                                         |       | SL-7970R<br>CLM-26         |
| MR135255                                                                               | Stabilizers Link |                                                                                     |                                                                                         |       |                            |
| MR267876<br>MR132551                                                                   | Stabilizers Link |  | PAJERO V6                                                                               |       | SL-7720L<br>CLM-16         |
| MR267877<br>MR132552                                                                   |                  |                                                                                     |                                                                                         |       | SL-7720R<br>CLM-15         |
| MR267873<br>MR132707                                                                   | Stabilizers Link |  | SPACE GRAR FRONT                                                                        | 1994- | SL-7760<br>CLM-17          |
| MR267875<br>MR112394<br>MB185476                                                       | Stabilizers Link |  | SPACE GRAR                                                                              | 1994- | SL-7765<br>CLM-19          |
| MR403771<br>4056A037<br>MR476595                                                       | Stabilizers Link |  | LANCER 欧蓝德后                                                                             | 2000- | SL-7875<br>CLM-18          |

|                                                                      |                  |                                                                                     |                                                                                                                                                                             |       |                              |
|----------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------------------------------|
| MR316436<br>4056A035                                                 | Stabilizers Link |    | MITSUBISHI SPACE RUNNER N63W N64W<br>MITSUBISHI STARION A187A<br>MITSUBISHI CHARIOT SPACE WAGON GRANDIS N84W N94W MITSUBISHI RVR N61W N64W N64WG N71W N73W N73WG N74W N74WG | 1988- | SL-7900R<br>CLM-20           |
| MR316435<br>4056A034                                                 |                  |                                                                                     |                                                                                                                                                                             |       | SL-7900L<br>CLM-21           |
| MB001622<br>MB241429<br>MB241798<br>MB001925                         |                  |    |                                                                                                                                                                             |       | K9232                        |
| MB598098<br>4056A138                                                 | Stabilizers Link |    | PAJERO V43 V45                                                                                                                                                              | 1991- |                              |
| MR333762<br>MR131732                                                 | Stabilizers Link |    | MITSUBISHI DIAMANTE ES<br>MITSUBISHI GALANT<br>CHRYSLER SEBRING DODGE STRATUS DODGE STRATUS R/T MITSUBISHI DIAMANTE                                                         | 1993- | K7432<br>18376               |
| MR316368<br>4056A015<br>51321-S2G-                                   | Stabilizers Link |    | LANCER FRONT VIRAGE                                                                                                                                                         |       | SL-7820L<br>CLM-10           |
| MR316369<br>4056A016<br>51320-S2G-                                   |                  |                                                                                     |                                                                                                                                                                             | 1994- | SL-7820R<br>CLM-9            |
| MN101368<br>508758                                                   | Stabilizers Link |   | CITROEN C-CROSSER EP<br>PEUGEOT 4007 GP<br>MITSUBISHI OUTLANDER II                                                                                                          | 2006- | SL-B010                      |
| MR131680<br>MR272116<br>4056A031<br>30873100<br>30884358<br>30871770 | Stabilizers Link |  | MITSUBISHI CARISMA DA<br>MITSUBISHI CARISMA Saloon DA<br>VOLVO S40 I VS<br>VOLVO V40 Estate VW                                                                              | 1995- | SL-7960<br>K750167<br>CLM-29 |
| MR374521<br>4056A106<br>MB267877                                     | Stabilizers Link |  | MITSUBISHI PAJERO CLASSIC V2_W<br>MITSUBISHI PAJERO III V60 V70 MITSUBISHI PAJERO SPORT K90                                                                                 | 1999- | SL-7840L<br>CLM-12<br>K90671 |
| MR374522<br>4056A105<br>MB267876                                     |                  |                                                                                     |                                                                                                                                                                             |       | SL-7840R<br>CLM-11<br>K90672 |
| MN184194<br>517849<br>46640-86Z00<br>5174245AA<br>96225858           | Stabilizers Link |  | OUTLANDER CW5W<br>GALANT FORTIS CY4A<br>PEUGEOT 4007<br>CITROEN C-CROSSER EP                                                                                                | 2005- | SL-B015R                     |
| 4156A014<br>517848<br>46630-86Z00<br>96225859                        |                  |                                                                                     |                                                                                                                                                                             | 景程VA  | SL-B015L<br>K750290          |
| MR589337                                                             | Stabilizers Link |  | MITSUBISHI ENDEAVOR BASE<br>MODEL MITSUBISHI ENDEAVOR XLS                                                                                                                   | 2004- | K750148                      |
| MR418052<br>4056A111                                                 | Stabilizers Link |  | PAJERO REAR<br>PAJERO V65W                                                                                                                                                  | 1999- | SL-7845L<br>CLM-14           |
| MR418053<br>4056A112                                                 | Stabilizers Link |                                                                                     |                                                                                                                                                                             |       | SL-7845R<br>CLM-13           |
| MB809354<br>MB879354<br>4056A021<br>48820-20010                      | Stabilizers Link |  | LANCER REAR                                                                                                                                                                 | 1991- | SL-7705                      |



|                                                                                     |                    |                                                                                     |                                                                                          |       |                             |
|-------------------------------------------------------------------------------------|--------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|-------|-----------------------------|
| MR316369<br>4056A016<br>54830-17010<br>54830-25010                                  | Stabilizers Link   |    | MITSUBISHI COLT V CJ_A CJ CP<br>MITSUBISHI LANCER VI CK/P_A<br>MITSUBISHI OUTLANDER I CU | 1995- | SL-7820R<br>CLKH-18R        |
| MR316368<br>4056A015                                                                |                    |                                                                                     |                                                                                          |       | SL-7820L<br>CLKH-18L        |
| MR344624<br>MR555883<br>MR586053                                                    | Stabilizers Link   |    | MITSUBISHI PAJERO SPORT K90 帕杰罗                                                          | 1997- |                             |
| MR131732<br>4056A019                                                                | Stabilizers Link   |    | GALANT 2.0                                                                               | 2000- | SL-7885                     |
| MB892981<br>4056A026<br>4D0505465D<br>25740375                                      | Stabilizers Link   |    | GALANT FRONT<br>Audi A8<br>Cadillac CTS                                                  | 1992- | SL-7750<br>K90670<br>K80564 |
| MR992309<br>54668-4N001                                                             | Stabilizers Link   |   | MITSUBISHI L200 K_T<br>MITSUBISHI L200 KB_T KA_T                                         |       | SL-7950L<br>CLM-25          |
| MR992310<br>54618-4N001<br>54823-H1000                                              |                    |                                                                                     |                                                                                          |       | SL-7950R<br>CLM-24          |
| MR589336                                                                            | Stabilizers Link   |  | MITSUBISHI ECLIPSE GS L4 2.4L 2378CC VIN F 4G69                                          | 2006- | K750030<br>CLM-23           |
| MR961477<br>4543200010                                                              | Stabilizers Link   |  |                                                                                          |       |                             |
| MR333763<br>MR297334<br>96403100                                                    | Stabilizers Link   |  | Mitsubishi Eclipse Dodge Stratus                                                         | 2004- | 18406<br>CLM-7<br>K7431     |
| MR297333<br>96403099                                                                |                    |                                                                                     | Mitsubishi Eclipse                                                                       | 2004- | 18407<br>CLM-8<br>K7430     |
| MB350577<br>MB501017<br>MR210221<br>MR455425<br>MR455426<br>SE000300<br>57730-33010 | AxialJoit Rack End |  | L300 P01V ETERNA<br>SPACE GEAR 4WD                                                       | 1983- | EV206<br>SR-7231<br>SR-7321 |
| MB501721<br>MB532281<br>MR131856                                                    | AxialJoit Rack End |  | GALANT RVR<br>N13W DODGE<br>2000GTX PLYMOUTH<br>LASER                                    | 1987- | SR-7380<br>CRM-9<br>EV236   |
| 4422A036                                                                            | AxialJoit Rack End |  | MITSUBISHI PAJERO IV MONTERO V87W/V97W                                                   | 2006- |                             |
| MR403099<br>57755-25000                                                             | AxialJoit Rack End |  | MITSUBISHI CEDIA Saloon CS_A                                                             | 1997- | AX0062                      |
| MR403027<br>3345797                                                                 | AxialJoit Rack End |  | MITSUBISHI CARISMA DA<br>MITSUBISHI CARISMA Saloon DA_ VOLVO V40                         | 1999- |                             |

|                                                                                                                                                                              |                       |                                                                                     |                                                                                                                      |       |                                                 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|-------|-------------------------------------------------|
| 4422A044<br>4422A004<br>MR589343<br>45503-52040                                                                                                                              | AxialJoit<br>Rack End |    | MITSUBISHI GALANT<br>DJ1A/DJ3A/DJ5A<br>Mitsubishi Eclipse                                                            | 2004- | ES800045<br>EV800045                            |
| MB870078<br>MR131857<br>MB351572                                                                                                                                             | AxialJoit<br>Rack End |    | MITSUBISHI EXPO LRV<br>MITSUBISHI SPACE RUNNER<br>N1W N2W<br>MITSUBISHI SPACE WAGON<br>N3W N4W                       | 1991- |                                                 |
| MB844695<br>MR131830<br>4422A079                                                                                                                                             | AxialJoit<br>Rack End |    | MITSUBISHI 3000 GT Z16A<br>MITSUBISHI SIGMA F16A<br>MITSUBISHI SIGMA Station<br>Wagon F07W                           | 1991- | CRM-14<br>EV800540                              |
| 4422A004<br>CW657353                                                                                                                                                         | AxialJoit<br>Rack End |    | MITSUBISHI ECLIPSE L4 2.4L<br>2378CC VIN F 4G69 GS                                                                   | 2004- | EV800045<br>ES4396                              |
| MR448255<br>83PAJERO-<br>MIN WR650                                                                                                                                           | AxialJoit<br>Rack End |    | MIN-PAJERO 飞腾                                                                                                        | 1998- |                                                 |
| 4410A172<br>4410A172T<br>4422A025                                                                                                                                            | AxialJoit<br>Rack End |    | TRITON KA4T<br>ZINGER                                                                                                | 2005- | SR-7940                                         |
| MR403100<br>4422A012<br>4422A057<br>4422A079<br>MR297155<br>MR297193<br>MR491403<br>MR491492<br>MR491673<br>MR491674<br>3812F1<br>400169<br>4410A011<br>51784191<br>4422A076 | AxialJoit<br>Rack End |   | OUTLANDER CW5W<br>OUTLANDER 3.0L<br>AIRTREK CU2W<br>SPACE WAGON N84W 欧蓝<br>德 PEUGEOT 4007 GP<br>CITROEN C-CROSSER EP | 2001- | SR-B010<br>SR-B050<br>CRM-26<br>EV800638        |
| PW550281<br>PW530031<br>PW530032                                                                                                                                             | AxialJoit<br>Rack End |  | PROTON WIRA                                                                                                          | 1993- | SR-7810<br>CRM-12                               |
| MB949343<br>MR333166<br>MR403872<br>MR594674<br>MR403872<br>45503-05020                                                                                                      | AxialJoit<br>Rack End |  | Mitsubishi Eclipse<br>GALANT Chrysler<br>Sebring Dodge Avenger                                                       | 1992- | EV350<br>SR-7750<br>SR-7880<br>CRM-23<br>CRM-15 |
| MR374835<br>MR374161                                                                                                                                                         | AxialJoit<br>Rack End |  | ADVENTURE<br>FREECA 富利卡                                                                                              | 1998- | SR-7780                                         |
| MR131830<br>4422A057                                                                                                                                                         | AxialJoit<br>Rack End |  | 3000 GT Z16A SIGMA<br>F16A F07W 西格玛                                                                                  | 1992- |                                                 |
| MC092281<br>MC081152                                                                                                                                                         | AxialJoit<br>Rack End |  | MITSUBISHI CANTER FD5<br>FB501 FD501                                                                                 |       | CRM-140<br>SR-7921                              |
| MC352178                                                                                                                                                                     | AxialJoit<br>Rack End |                                                                                     | STEERING GEAR I                                                                                                      |       | CRM-141                                         |



|                                                           |                       |                                                                                     |                                                                                                                   |                            |                                        |
|-----------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|----------------------------|----------------------------------------|
| MR510267                                                  | AxialJoit<br>Rack End |    | MITSUBISHI PAJERO CLASSIC<br>V2_W<br>MITSUBISHI PAJERO III V60<br>V70 MITSUBISHI PAJERO<br>SPORT K90              | 1999-                      | SR-7840<br>EV800441<br>CRM-20          |
| MB553249<br>ES2936<br>ES1215                              | AxialJoit<br>Rack End |    | MIRAGE                                                                                                            | 1987-                      | SR-7390<br>EV215                       |
| MB532046<br>MB347666<br>MB489606<br>E1FZ3280B<br>PW500415 | AxialJoit<br>Rack End |    | MITSUBISHI COLT II C1_A<br>MITSUBISHI LANCER III C1_A<br>C6_A<br>MITSUBISHI LANCER III Station<br>Wagon C1_V C3_V | 1983-                      | EV183<br>SR-7240<br>SR-7370            |
| MB489606<br>PW500415                                      | AxialJoit<br>Rack End |    | MITSUBISHI LANCER-FIORE<br>MITSUBISHI MIRAGE                                                                      |                            |                                        |
| MR244901<br>3345797                                       | AxialJoit<br>Rack End |    | MITSUBISHI CARISMA DA<br>MITSUBISHI CARISMA Saloon<br>DA<br>VOLVO S40 I VS<br>VOLVO V40 F-16-18W                  | 1995-                      | SR-7960<br>CRM-31                      |
| MR455091<br>MR455092                                      | AxialJoit<br>Rack End |    | MITSUBISHI SPACE WAGON<br>N9 W N8 W                                                                               |                            |                                        |
| MB532972                                                  | AxialJoit<br>Rack End |   | SPACE GEAR 4WD                                                                                                    | 1986-                      | SR-7320                                |
| 4410A173T<br>4410A173                                     | AxialJoit<br>Rack End |  | TRITON 4x4<br>KB4T                                                                                                | TRITON<br>2005-            | SR-7950                                |
| MR491358<br>PW890355<br>45A2164<br>4422A056<br>4422A078   | AxialJoit<br>Rack End |  | LANCER<br>CS1A CS2A                                                                                               | LANCER<br>2000-            | EV80587<br>ES4244<br>SR-7870<br>CRM-22 |
| MB350718<br>MB501530                                      | AxialJoit<br>Rack End |  | MIRAGE<br>COLT<br>COLT                                                                                            | DODGE<br>PLYMOUTH<br>1983- | SR-7241<br>EV196                       |
| MB532971<br>MR210221                                      | AxialJoit<br>Rack End |  | SPACE GEAR 2WD                                                                                                    | 1986-                      | SR-7310                                |
| MB243329                                                  | AxialJoit<br>Rack End |  | CORDIA                                                                                                            | 1982-                      | SR-7180<br>EV197                       |
| MB315586<br>MB243373                                      | AxialJoit<br>Rack End |  | MITSUBISHI COLT I A15 A                                                                                           | 1983-                      | SR-7230                                |
| MR151970                                                  | AxialJoit<br>Rack End |  | MITSUBISHI L400 PA3W/PA4W<br>MITSUBISHI DELICA SPACE<br>GEAR/CARGO PA/PB/PC                                       |                            | CRM-30                                 |
| MB831042                                                  | Idler Arm             |  | PAJERO V34V<br>猎豹                                                                                                 | 1990-                      | SI-7720                                |
| MB241830<br>MB698532                                      | Idler Arm             |  | MITSUBISHI PAJERO I L04_G<br>L14_G<br>MITSUBISHI PAJERO I Open<br>Off-Road Vehicle L04_G                          |                            |                                        |





|                                  |           |                                                                                     |                                                                     |    |                |
|----------------------------------|-----------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------|----|----------------|
| MB241423                         | Idler Arm |    | mitsubishi L200 K_T                                                 |    | K9378          |
| MB180102                         |           |                                                                                     |                                                                     |    |                |
| MB241421<br>MB241422             | Idler Arm |    |                                                                     |    |                |
| MB527228                         | Idler Arm |    | mitsubishi L200 K__T                                                |    | K9486<br>K9004 |
| MR241000<br>MR241030             | Idler Arm |    |                                                                     |    |                |
| MR296273<br>MR296509<br>MR344654 | Idler Arm |    | mitsubishi L200 K T<br>mitsubishi PAJERO SPORT<br>K90               |    |                |
| MR296272                         | Idler Arm |   |                                                                     | 速跑 |                |
| MB166425                         | Idler Arm |  | MITSUBISHI L 300 Bus<br>LO3_P/G LO_2P<br>MITSUBISHI L 300 Box LO3_P |    |                |
| MT142322<br>MB006306<br>MB006303 | Idler Arm |  | MITSUBISHI DELICA L300 T100<br>T100 T120 T121                       |    |                |
| MR296271                         | Idler Arm |  | MITSUBISH L200 K_T                                                  |    |                |
| MB283147                         | Idler Arm |                                                                                     |                                                                     |    |                |
| MB315769                         | Idler Arm |  | MITSUBISHI L300 Bus LO3_P/G<br>LO_2P                                |    |                |
| MB166423<br>MB166424             | Idler Arm |  |                                                                     |    |                |
| MB283150                         | Idler Arm |  |                                                                     |    |                |

|                                              |               |                                                                                     |                                                                                                                                        |  |                   |
|----------------------------------------------|---------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--|-------------------|
| MR592120<br>MR592134<br>MR296508<br>MR376996 | PITMAN<br>ARM |    | STRADA 4x4 MONIERO<br>CHALLENGER K74T K96W<br>速跑                                                                                       |  | K90333            |
| MB598489                                     | PITMAN<br>ARM |    | MITSUBISHI PAJERO I L04_G<br>L14_G                                                                                                     |  |                   |
| MB241973                                     | PITMAN<br>ARM |    | MITSUBISHI PAJERO I Open<br>Off-Road Vehicle L04_G                                                                                     |  |                   |
| MB241166<br>MB166281                         | PITMAN<br>ARM |    | MITSUBISHI L 200 K__T                                                                                                                  |  | K9130             |
| MR241029                                     | PITMAN<br>ARM |    | MITSUBISHI L200 K_T                                                                                                                    |  |                   |
| MB241448                                     | PITMAN<br>ARM |    | MITSUBISHI LANCER F II A17                                                                                                             |  |                   |
| MB241884                                     | PITMAN<br>ARM |    | MITSUBISHI PAJERO I Open<br>Off Road Vehicle L04_G                                                                                     |  | SP-7350           |
| MB241168                                     | PITMAN<br>ARM |  | MITSUBISHI L200 K_T                                                                                                                    |  | K9388             |
| MB006304<br>MB006302<br>MT142320             | PITMAN<br>ARM |                                                                                     |                                                                                                                                        |  | SP-7080           |
| MB241973                                     | PITMAN<br>ARM |  | MITSUBISHI PAJERO I L04_G<br>L14_G<br>MITSUBISHI PAJERO I Open<br>Off-Road Vehicle L04_G                                               |  | SP-7351           |
| MB598489                                     | PITMAN<br>ARM |  | MITSUBISHI PAJERO I L04_G<br>L14_G                                                                                                     |  | SP-7710           |
| MB831040<br>MR592811                         | PITMAN<br>ARM |  | MITSUBISHI PAJERO CLASSIC<br>V2_W<br>MITSUBISHI PAJERO II V3_W<br>V2_W V4_W<br>MITSUBISHI PAJERO II Open<br>Off-Road Vehicle V2_W V4_W |  | CPM-12<br>SP-7720 |

|                                                                      |             |                                                                                     |                                                                                                                                                                                                                                  |        |         |
|----------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|---------|
| MR162581                                                             | Control Arm |    |                                                                                                                                                                                                                                  |        |         |
| MR162582                                                             |             |                                                                                     |                                                                                                                                                                                                                                  |        |         |
| MR296296<br>MR162580<br>MR325576<br>MB912510<br>MR972466             | Control Arm |    | MITSUBISHI ECLIPSE I D2A<br>MITSUBISHI ECLIPSE II D3<br>MITSUBISHI GALANT V E5A E7A E8A<br>MITSUBISHI GALANT V Saloon E5A E7A E8A<br>MITSUBISHI GALANT VI EA<br>MITSUBISHI GALANT VI Estate EA<br>Chrysler Sebring Dodge Avenger | CBM-24 |         |
| K200245                                                              |             |                                                                                     |                                                                                                                                                                                                                                  |        |         |
| MR296295<br>MR325005<br>MR162579<br>MR325577<br>MB912509<br>MR972465 |             |                                                                                     |                                                                                                                                                                                                                                  | CBM-25 |         |
| MR369795<br>MR369796<br>MR455737<br>MR455738<br>MR554375<br>MR554376 | Control Arm |    | MITSUBISHI ECLIPSE<br>DODGE STRATUS<br>CHRYSLER SEBRING                                                                                                                                                                          | 2000-  | 520-538 |
| PW826060<br>PW826061<br>MB931441<br>MB931442                         | Control Arm |   |                                                                                                                                                                                                                                  |        |         |
| MR210444                                                             | Control Arm |  |                                                                                                                                                                                                                                  |        |         |
| PW521816                                                             | Control Arm |  |                                                                                                                                                                                                                                  |        |         |
| MN164137<br>MN164138                                                 | Control Arm |  |                                                                                                                                                                                                                                  |        |         |
| 14124701                                                             |             |                                                                                     |                                                                                                                                                                                                                                  |        |         |
| MR414939                                                             | Control Arm |  | MITSUBISHI PAJERO PININ<br>H6_W H7_W 飞腾                                                                                                                                                                                          | 1999-  |         |
| MR414940                                                             |             |                                                                                     |                                                                                                                                                                                                                                  |        |         |
| MR319067<br>MR210222                                                 |             |  |                                                                                                                                                                                                                                  |        |         |
| MR414939-01<br>MR592351                                              |             |  |                                                                                                                                                                                                                                  |        |         |

|                                                                                                                                               |             |                                                                                     |                                                                                                                                                                                   |       |                                             |
|-----------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|---------------------------------------------|
| 4013A009<br>4013A010<br>4013A281<br>4013A282<br>3521V0<br>3520V0<br>3520X9<br>3521R1<br>5105041AD<br>5105040AD                                | Control Arm |    | MITSUBISHI OUTLANDER CW<br>MITSUBISHI DELICA D5 CV5W<br>MITSUBISHI LANCER<br>CY2A/CY3A/CY4A<br>PEUGEOT 4007<br>CITROEN C-CROSSER EP<br>Dodge Caliber Jeep<br>Compass Jeep Patriot |       | RK620066<br>RK620065<br>521-305<br>507-1845 |
| MB491345<br>MB809220<br>30818096<br>30818097<br>PW530954<br>MB809221<br>308180975<br>MB491346<br>PW530955<br>MR491367<br>PW530953<br>MR491346 | Control Arm |    | CARISMA DA<br>COLT CA A<br>LANCER CB CK CY<br>VOLVO S40 V40                                                                                                                       | 1992- | 520-844<br>RK640894<br>K620039              |
| MB907163<br>MB907115<br>MB912077<br>MB907165<br>MB907164<br>MB907116<br>MB912078<br>MB907166                                                  | Control Arm |   | LANCER C6 C7 CB CD CK CP                                                                                                                                                          | 1988- |                                             |
| MR130983                                                                                                                                      | Arm Bush    |  |                                                                                                                                                                                   |       |                                             |
| MB808910<br>MR102654<br>30872511                                                                                                              | Arm Bush    |  |                                                                                                                                                                                   |       | K200072                                     |
| MB809223<br>MB910842<br>MR491348<br>MB809222<br>MR491347                                                                                      | Control Arm |  | MITSUBISHI COLT V CJA CJ<br>CP MITSUBISHI LANCER V<br>MITSUBISHI SPACE STAR<br>DGA DG0 VOLVO S40 I                                                                                |       | 520-842<br>K80641<br>K80642                 |
|                                                                                                                                               |             |                                                                                     |                                                                                                                                                                                   |       |                                             |
|                                                                                                                                               |             |                                                                                     |                                                                                                                                                                                   |       |                                             |
| MB910841<br>MR491347<br>MB809222                                                                                                              |             |                                                                                     |                                                                                                                                                                                   |       | K80642                                      |
| MR124879<br>MR296093<br>MB831035<br>MR296095<br>MB831036<br>MR124880<br>MR296094<br>MR296096                                                  | Control Arm |  | MITSUBISHI L200<br>PAJERO V60 V70 V2 V4<br>帕杰罗V32 猎豹<br>GALLOPER I 2.5 TD                                                                                                         |       |                                             |
| MB633820<br>MR124880                                                                                                                          | Arm Bush    |  |                                                                                                                                                                                   |       |                                             |

|                                                                                              |               |                                                                                     |                                                                                         |                               |           |                       |
|----------------------------------------------------------------------------------------------|---------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-------------------------------|-----------|-----------------------|
| MB518806<br>MB891787<br>MB518960<br>MB518807<br>MB891788<br>MB518961<br>MB573222<br>MB573223 | Control Arm   |    | COLT C5<br>C6 C7                                                                        | LANCER                        | 1986-     |                       |
| 54590-01E00                                                                                  |               |    |                                                                                         |                               |           |                       |
| MB912507<br>MB912505<br>MR162803<br>MB912506<br>MB912508<br>MR162804                         | Control Arm   |    | ECLIPSE D2 D3<br>GALANT E5 E7 E8 EA<br>Chrysler Sebring<br>Avenger                      | Dodge                         | 1988-     |                       |
| MB892320<br>MR162803                                                                         |               |    |                                                                                         |                               |           |                       |
| MR961392<br>MR961391<br>MN101742<br>MN101743<br>4013A132<br>4013A131<br>MN101741             | Control Arm   |   | OUTLANDER CU<br>MITSUBISHI LANCER CS<br>CHERY FORA A21<br>MITSUBISHI DINGO<br>CQ1A/CQ2A |                               | 2003-     | 欧蓝德<br>CU4 CS3<br>CS5 |
| MR403441<br>A21-<br>P12000070                                                                | Arm Bushing   |  |                                                                                         |                               |           |                       |
| MR241342<br>MR439702                                                                         | Control Arm   |  | COLT CJ<br>CK/P<br>Mitsubishi Mirage<br>MITSUBISHI LANCER CK1A<br>CK2A                  | LANCER                        | 1995-2005 | 520-854               |
| MR241341<br>MR439701                                                                         |               |                                                                                     |                                                                                         |                               | 菱帅 03款    | 520-583               |
| MR130982                                                                                     |               |                                                                                     |                                                                                         |                               |           |                       |
| MB808910<br>MB102654<br>MB871430                                                             |               |  |                                                                                         |                               |           |                       |
| MB808909<br>MB102653<br>30851257                                                             |               |                                                                                     |                                                                                         |                               |           |                       |
| MB175545<br>MB109893<br>MB349475                                                             | Control Arm   |  | L300 Bus LO3 P/G L0 2P<br>利卡前上                                                          | 富                             | 1984-     |                       |
| MB109539<br>K9004                                                                            | NNER<br>SHAFT |  | Dodge Ram 50<br>Mighty Max                                                              | Mitsubishi<br>Mitsubishi L200 |           | CIKH-2                |
| MB527157<br>MB527159<br>MB860408<br>MB527160<br>MB527511                                     | Control Arm   |  | MITSUBISHI L200 K T                                                                     |                               | 1986-     |                       |
| MB109512                                                                                     | Control Arm   |  | MITSUBISHI L200 K T<br>Dodge Ram 50<br>Mighty Max                                       | Mitsubishi                    | 1986-1996 | 521-309               |
| MB109513                                                                                     |               |                                                                                     |                                                                                         |                               | 富利卡前<br>下 |                       |

|                                                                                                                   |             |                                                                                     |                                                                                                                                    |            |                                     |
|-------------------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------------------------|
| MB349943                                                                                                          | Control Arm |    | L300 Platform/Chassis L03P                                                                                                         | 1980       |                                     |
| MB349944                                                                                                          |             |                                                                                     | 得利卡                                                                                                                                |            |                                     |
| MB430112<br>MB527383<br>MB598017<br>MB598018<br>MB430230<br>MB698511<br>54510-43152<br>54510-43151<br>54510-43150 | Control Arm |    | L300 P0P1 P2 H100                                                                                                                  | 1986-      |                                     |
| MB430145<br>MR319537                                                                                              |             |    |                                                                                                                                    |            |                                     |
| MR496794<br>4010A038<br>MR496793<br>4010A037<br>4010A041<br>4010A042                                              | Control Arm |    | MITSUBISHI PAJERO III V60<br>V70 V73上悬挂<br>MITSUBISHI PAJERO III<br>MONTERO V65W V75W<br>MITSUBISHI PAJERO IV<br>MONTERO V87W V97W | 2000-      |                                     |
| MR519398                                                                                                          | Arm Bushing |    |                                                                                                                                    |            |                                     |
| MB109648<br>MB109647<br>MB633264<br>HB212003<br>HB212001<br>HB212002<br>HB212004                                  | Control Arm |   | HYUNDAI GALLOPER JK-01<br>MITSUBISHI GALLOPER JK-01                                                                                |            |                                     |
| MB109684                                                                                                          |             |  |                                                                                                                                    |            |                                     |
| MB109662                                                                                                          |             |  |                                                                                                                                    |            |                                     |
| HB212100<br>HB212100<br>ZB212100                                                                                  |             |  |                                                                                                                                    |            |                                     |
| MR403419<br>4013A255<br>4013A273<br>A21-2909010                                                                   | Control Arm |  | LANCER Saloon CS                                                                                                                   | 2002-      |                                     |
| MR403420<br>4013A274<br>MR455070<br>4013A256                                                                      |             |                                                                                     |                                                                                                                                    |            | RK620345<br>520-886                 |
| MR403441<br>A21-<br>B.12909070                                                                                    |             |  |                                                                                                                                    | 奇瑞A5/奇瑞A21 |                                     |
| MR403440<br>MN101438                                                                                              |             |  |                                                                                                                                    |            |                                     |
| K80373                                                                                                            |             |  |                                                                                                                                    |            | SB-7872<br>CBM-36<br>MR403420<br>-1 |
| A21-2909060                                                                                                       |             |  | 奇瑞A5/奇瑞A21                                                                                                                         |            |                                     |



|                                                                                  |             |                                                                                     |                                                                                                                                                                                              |           |                                     |
|----------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------------------------------|
| 4013A087<br>4013A088                                                             | Control Arm |    | MITSUBISHI NATIVA KH8W<br>MITSUBISHI TRITON KB9T<br>MITSUBISHI PAJERO/MONTERO SPORT<br>CHALLENGER KH#<br>MITSUBISHI L200<br>MITSUBISHI L200 SPORTERO<br>KB9T 4WD MITSUBISHI L200<br>KB4T 4WD |           |                                     |
| MR510420                                                                         |             |    |                                                                                                                                                                                              |           |                                     |
| MR510417<br>MR992256                                                             |             |    |                                                                                                                                                                                              |           |                                     |
| 4010A013<br>MR992261                                                             | Control Arm |    | PAJERO V60 V70 V80 V90<br>L200 KAOT                                                                                                                                                          |           |                                     |
| MR519398<br>4010A042                                                             |             |    |                                                                                                                                                                                              |           |                                     |
| SW608911                                                                         | Control Arm |    | MITSUBISHI<br>DISCRIPTION:CONTROL 菱利                                                                                                                                                         |           |                                     |
| MB109343<br>MB303856<br>MB109344                                                 | Control Arm |    | L300 LO3 P/G L0 2P                                                                                                                                                                           |           |                                     |
| MR210430<br>MR210431                                                             | Control Arm |   | PREECA                                                                                                                                                                                       | 1997-     |                                     |
| MR241023<br>MR241024                                                             | Control Arm |  | MITSUBISHI L200 K T                                                                                                                                                                          | 1986-1996 |                                     |
| MN161705<br>MN186655<br>MN161706<br>MN186656                                     | Control Arm |  | GALANT CRUNDER                                                                                                                                                                               | 2004-     |                                     |
| MN184123                                                                         |             |  |                                                                                                                                                                                              |           |                                     |
| K500068                                                                          |             |  |                                                                                                                                                                                              |           | MN161705<br>-1<br>MN186655<br>1 CRM |
| MB912515<br>MR162571<br>MR162573<br>MR124293<br>MB912516<br>MR162574<br>MR124294 | Control Arm |  | MITSUBISHI-DIAMANTE                                                                                                                                                                          | 1997-     |                                     |
| MR162572                                                                         |             |                                                                                     |                                                                                                                                                                                              |           |                                     |
| MR491962<br>A21-2919210                                                          | Control Arm |  | MITSUBISHI-LANCER                                                                                                                                                                            | 2002-     |                                     |

|                                                                                              |             |                                                                                     |                                                                                                                       |       |                     |
|----------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|-------|---------------------|
| 4013A209<br>4013A210<br>MN133171<br>MN133172<br>4013A225<br>4013A224<br>MR496795<br>MR496796 | Control Arm |    | PAJERO V73 MONTERO<br>2001款V73                                                                                        |       |                     |
| MR992385<br>MR992386<br>4010A017<br>4010A018                                                 | Control Arm |    | TRITON KA4T 4X2                                                                                                       | 2006- |                     |
| 4013A091<br>4013A092                                                                         | Control Arm |    | TRITON KA4T 4X2                                                                                                       | 2006- |                     |
| MR296027<br>MR241025<br>MR296028<br>MR241026                                                 | Control Arm |    | L200 2WD                                                                                                              |       |                     |
| MB527162<br>MB527512<br>MB527161<br>MB527511                                                 | Control Arm |    | L200 4WD                                                                                                              | 2004- |                     |
| MB598545<br>MB598087<br>MB598546<br>MB598088                                                 | Control Arm |   | MITSUBISHI DELICA Box P0_W<br>P1_W                                                                                    |       |                     |
| MB430200<br>54449-43000                                                                      |             |  |                                                                                                                       | 得利卡前上 |                     |
| MB430201                                                                                     |             |  |                                                                                                                       |       |                     |
| MR316053<br>MR589033<br>MR316054<br>MR589034                                                 | Control Arm |  | MITSUBISHI CHARIOTSPACE<br>WAGON GRANDIS N84W<br>N94W MITSUBISHI RVR<br>N61W N64W N64WG N71W<br>N73W N73WG N74W N74WG | 1997- |                     |
| MR316074<br>4013A045                                                                         | Arm Bushing |  |                                                                                                                       |       |                     |
| MR491911<br>4110A085                                                                         | Control Arm |  | MITSUBISHI LANCER CS<br>MITSUBISHI DION CR5W<br>CR6W CR9W<br>MITSUBISHI OUTLANDER CW                                  | 2000- | RK640993<br>521-545 |
| 4110A012<br>MN100110<br>MR102012<br>MR244851<br>MR403464                                     |             |  |                                                                                                                       |       |                     |
| MN100109<br>4110A033<br>MR554111                                                             |             |  |                                                                                                                       |       |                     |
| MN100075<br>4110A086<br>MR594949<br>MN100086                                                 |             |  | MITSUBISHI OUTLANDER CU<br>MITSUBISHI LANCER CS<br>DODGE CALIBER                                                      | 2002- |                     |

|                                                                                                                                                                          |             |                                                                                     |                                                                                                                                       |             |         |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------|-------------|---------|
| 4117A007<br>4117A005<br>5175EG<br>MR403485<br>A21-2919410                                                                                                                | Control Arm |    |                                                                                                                                       | 2000-       | 521-980 |
| MN100110<br>MR403464<br>MN100086S<br>MR369662<br>MR369660<br>GJ6A-28-450<br>GP9A-28-450<br>MB864931<br>MB864932<br>MN100109<br>MR223673<br>MR554111                      |             |    | MITSUBISHI OUTLANDER II<br>CW_W MITSUBISHI LANCER<br>SPORTBACK CX_A<br>CHRYSLER SEBRING JR<br>PEUGEOT 4007 GP<br>CITROEN C-CROSSER EP | 新欧蓝德<br>CW5 |         |
| MB809232<br>MB809230<br>MB809231<br>MB809233                                                                                                                             | Control Arm |    | COLT CA CJ<br>LANCER CB/D CK/P<br>VOLVO V40                                                                                           | 1992-       |         |
| MB809239<br>05105272AB<br>MR102012<br>MR244851<br>MR403464<br>30620972                                                                                                   |             |    |                                                                                                                                       |             |         |
| 4113A037<br>4113A038<br>7632A366                                                                                                                                         | Control Arm |  | MITSUBISHI PAJERO 欧蓝德<br>后 Citroën C-Crosser<br>PEUGEOT 4007                                                                          | 2007-       |         |
| MN125431<br>MN125433                                                                                                                                                     | Control Arm |  | V73后 MITSUBISHI<br>PAJERO III V60 V70<br>MITSUBISHI PAJERO IV V80<br>V90                                                              |             |         |
| MR374672                                                                                                                                                                 | Arm Bush    |  |                                                                                                                                       |             |         |
| 4013A135<br>4013A150<br>4013A136<br>MN186217<br>MN186218<br>MN186218<br>4013A169<br>MN150103<br>MN150104<br>4013A033<br>4013A034<br>4013A175<br>4543300707<br>4543300807 | Control Arm |  | MITSUBISHI COLT<br>Z32A/Z34A/Z36A/Z37A/Z38A/Z3<br>9A SMART FORFOUR 454                                                                | 2004-       |         |

|                                                                                                        |             |                                                                                     |                                                                                                                                                         |       |                              |
|--------------------------------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------------------------------|
| MB912512<br>MR162582<br>MR296290                                                                       | Control Arm |    | MITSUBISHI ECLIPSE I D2_A<br>MITSUBISHI GALANT V E5_A<br>E7_A E8_A<br>MITSUBISHI ECLIPSE II D3                                                          | 1989- | K80436<br>SA-7752R           |
| MB912511<br>MB912513<br>MR162581<br>MR162583<br>MR296319<br>MR296287<br>MR296289<br>MR325251           |             |                                                                                     |                                                                                                                                                         |       | K80437<br>K80577<br>SA-7752L |
| PW800042                                                                                               | Control Arm |    |                                                                                                                                                         |       |                              |
| MB917165<br>MB917166                                                                                   | Control Arm |    |                                                                                                                                                         |       |                              |
| MB241341<br>PW820083<br>MR916133<br>MR911570<br>MR297241<br>4013A046<br>3088746<br>3088896<br>30888962 | Control Arm |   | MITSUBISHI CARISMA DA<br>MITSUBISHI ACE STAR DG_A<br>DG0 PROTONPERSONA 400<br>Hatchback C9C C9S<br>PROTONWIRA<br>PROTONWIRA Hatchback<br>PROTONGEN 2 CM | 1994- |                              |
| MB241342<br>MR911569<br>PW820084<br>MR916134<br>MR297242                                               |             |                                                                                     |                                                                                                                                                         | 宝腾    |                              |
| MR130982                                                                                               | Arm Bush    |  |                                                                                                                                                         |       |                              |
| MB808909<br>MB871429                                                                                   |             |  |                                                                                                                                                         |       |                              |
| MR414940<br>MR414939                                                                                   | Control Arm |  | MITSUBISHI MONTERO<br>MITSUBISHI PAJERO PININ<br>H6_W H7_W                                                                                              | 飞腾    |                              |
| MN101472<br>MN101471                                                                                   | Control Arm |  | 北京欧蓝德                                                                                                                                                   |       |                              |
| MB860832<br>MN161354                                                                                   | Control Arm |  | MITSUBISHI PAJERO II V3_W<br>V2_W V4_W<br>MITSUBISHI PAJERO II Open<br>Off-Road Vehicle V2_W                                                            |       |                              |
| MB860831<br>MN161353                                                                                   |             |                                                                                     |                                                                                                                                                         | 猎豹下悬挂 |                              |

|                                              |                     |                                                                                     |                                                                                                                                                                              |       |         |
|----------------------------------------------|---------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|---------|
| MR508131<br>4110A077<br>MN133703<br>4110A083 | Control Arm         |    | MITSUBISHI PAJERO V73W                                                                                                                                                       |       |         |
| MR519399                                     |                     |                                                                                     |                                                                                                                                                                              |       |         |
| MR508132<br>4110A078<br>MN133704<br>4110A084 |                     |                                                                                     |                                                                                                                                                                              | V73后  |         |
| MN150412<br>MR296268                         | Control Arm         |    | MITSUBISHI L200 K__T<br>MITSUBISHI PAJERO SPORT K90                                                                                                                          |       |         |
| MB109684                                     |                     |                                                                                     |                                                                                                                                                                              |       |         |
| MB633870<br>54564-H1000                      |                     |                                                                                     |                                                                                                                                                                              |       |         |
| MN150411<br>MR296267                         |                     |                                                                                     |                                                                                                                                                                              | 速跑    |         |
| MN100109<br>MR554111                         | Control Arm         |   | MITSUBISHI OUTLANDER CU<br>MITSUBISHI LANCER CS<br>MITSUBISHI OUTLANDER CW<br>MITSUBISHI GALANT<br>DJ1A/DJ3A/DJ5A MITSUBISHI<br>ECLIPSE DK2A/DK4A USA<br>MITSUBISHI ENDEAVOR | 2000- | 521-981 |
|                                              |                     |                                                                                     |                                                                                                                                                                              |       |         |
|                                              |                     |                                                                                     |                                                                                                                                                                              |       |         |
| MB378373                                     | Steering Joint      |                                                                                     |                                                                                                                                                                              |       |         |
| MT141247-01                                  | Inner Arm Shaft Kit |  | Mitsubishi Delica L300                                                                                                                                                       |       |         |

|                                              |                        |                                                                                     |                                                                                                                                                                              |       |         |
|----------------------------------------------|------------------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|---------|
| MR508131<br>4110A077<br>MN133703<br>4110A083 | Control Arm            |    | MITSUBISHI PAJERO V73W                                                                                                                                                       |       |         |
| MR519399                                     |                        |                                                                                     |                                                                                                                                                                              |       |         |
| MR508132<br>4110A078<br>MN133704<br>4110A084 |                        |                                                                                     |                                                                                                                                                                              | V73后  |         |
| MN150412<br>MR296268                         | Control Arm            |    | MITSUBISHI L200 K__T<br>MITSUBISHI PAJERO SPORT<br>K90                                                                                                                       |       |         |
| MB109684                                     |                        |                                                                                     |                                                                                                                                                                              |       |         |
| MB633870<br>54564-H1000                      |                        |                                                                                     |                                                                                                                                                                              |       |         |
| MN150411<br>MR296267                         |                        |                                                                                     |                                                                                                                                                                              | 速跑    |         |
| MN100109<br>MR554111                         | Control Arm            |   | MITSUBISHI OUTLANDER CU<br>MITSUBISHI LANCER CS<br>MITSUBISHI OUTLANDER CW<br>MITSUBISHI GALANT<br>DJ1A/DJ3A/DJ5A MITSUBISHI<br>ECLIPSE DK2A/DK4A USA<br>MITSUBISHI ENDEAVOR | 2000- | 521-981 |
|                                              |                        |                                                                                     |                                                                                                                                                                              |       |         |
|                                              |                        |                                                                                     |                                                                                                                                                                              |       |         |
| MB378373                                     | Steering Joint         |                                                                                     |                                                                                                                                                                              |       |         |
| MT141247-01                                  | Inner Arm<br>Shaft Kit |  | Mitsubishi Delica L300                                                                                                                                                       |       |         |



#### CONTACTS:

 [info@javiddo.com](mailto:info@javiddo.com)

 Office: +8615258908844  
Showroom: +8619700930434

 [www.javiddo.com](http://www.javiddo.com)  
[www.hellperglobal.com](http://www.hellperglobal.com)

 Office address: China, Zhenjiang , Jinhua city,  
Yiwu city, Futian road No.6-8, World Trade  
Center, Floor 53, Room No.5308-5309

Showroom address: China, Zhenjiang ,  
Jinhua city, Yiwu International Trade City,  
District 5, Gate 110, No.69235

#### SOCIAL MEDIA:

 Javiddo Group

 Javiddo Group

 Javiddo Group

 javiddogroup  
hellper.global

 javiddogroup  
hellper.global